

Spares



FACTORY SERVICE INCLUDES

1. Visual check for damage.
2. Cover - inspect and clean.
3. Buoyancy Chamber tested at 100mb for 16 hours.
4. Full CO2 Gas flow and Automatic unit check.
Includes piercing test.
5. Check and weigh CO2 cylinder.
6. Oral inflation valve check.
7. Whistle and Light (where fitted) check.
8. Change Bobbin/ Pill / Capsule in auto-unit.
9. Change all Gaskets, refit unit and CO2 cylinder.
10. Check unit torqued up.
11. Check Belts and buckles.

REPAIR. IT MAY BE NECESSARY WHEN INSPECTION REVEALS DAMAGE. SEE PRICE LIST FOR REPAIRS.



VISIBLE SAFETY

All ASPLI and SECUMAR Lifejackets have a Service Badge fitted to the Waist Belt indicating the Month/ Year when next inspection is due.



Usual 10 Day Service